AXIS AIRCRAFT SALES, Inc.

P. O. Box 777, Penrose, NC 28766 Office: (828) 883-5841 Mobile: (828) 551-2201 Fax: (828) 883-5647 Skype: chris.baker49 e-mail:<u>cbaker49@aol.com</u>

1981 LEARJET 35A

AIRFRAME: 12,416 Hrs Total Time

ENGINES: Garrett TFE 731-2-2B (Engines enrolled on MSP Gold)

Left Engine: 12,416 Hrs TTSN Right Engine: 11,764 Hrs TTSN

EXTERIOR: New in July 2004. Overall Matterhorn White with Black Stripes between Cutter Maroon Stripes.

- INTERIOR: Newly Refurbished. Eight Passenger Executive Interior. Soft Gray Leather with Dark Gray Accents. Complementing Light Gray Carpet. Aft Three Place Couch. Two Rear Facing Chairs. Two Forward Chairs. Belted Lav.
- AVIONICS: Dual Collins VHF-20A COM's Dual Collins VIR-30 NAV's Dual Collins ADF-60 ADF's Dual Collins TDR-90 Transponders Collins DME-40 DME King KFH-950 HF COM w SELCAL MFD Bendix King KMD-850 Multifunction Display w Vertical Profile Radar Universal UNS-1M FMS Collins FIS-84 Flight Director System FC-200 Autopilot Bendix King KGP-560 EGPWS GPS Garmin 400 w Terminal Weather Honeywell BA-250 Altimeter Honeywell AZ-252 Air Data Computer

ADDITIONAL EQUIMENT:

Cargo DoorN1 Deec Engine Computer UpgradeAeronca Thrust ReversersRosen Sun VisorRVSM CertifiedCockpit Voice RecorderDrag ChuteVisor

MAINTENANCE STATUS:

12 Year & 12,000 Hr Inspections c/w July 2004 at 11,039 hrs

3,000 landing Inspections c/w at 8,524 landings

6,000 landing Inspections c/w at 5,555 landings

A inspections c/w October 2009 at 12,148 hrs

B Inspections c/w October 2009 at 12,148 hrs

C & D Inspections c/w July 2006 at 11,694 hrs

Aircraft is offered subject to prior sale, and/or removal from the market. Specifications are subject to personal inspection of the aircraft.