

AXIS AIRCRAFT SALES Inc.

P. O. Box 777, Penrose, NC 28766

Office: 828-883-5841 Cell: 828-551-2201 Skype: chris.baker49 Fax: 828-883-5647

www.axisaircraftsales.com Email: cbaker49@aol.com

1985 Westwind II

Airframe: 7,173 Hours 4,393 Landings

Engines: Honeywell TFE731-3 On MSP Gold Contract
Left: 269 Hours to next MPI 1,721 Hours to next CZI
Right: 269 Hours to next MPI 1,721 Hours to next CZI

Exterior: 2005 Overall White and Slate Gray with Metallic Silver and Blue Trim.

Interior: 2005 Eight Passenger Executive Interior Configuration. Aft Cabin Four Place Club Seating with Two Foldout Executive Writing Tables. Single left side Forward Facing Chair opposite a right side Three Place Divan. Chairs are upholstered in Light Gray Leather. The Divan is covered in Royal Blue Cloth. Teak Woodwork and Cabinetry. Slimline Refreshment Center with Ice Drawer and Beverage Storage. Cabin Entertainment System with a 10.4 inch bulkhead Monitor and Air Show 400 Moving Map Display. Aft Enclosed Flushing Toilet with Vanity.

Avionics: Collins EFIS-85A Five Tube EFIS System
Dual Collins FCS-80 Flight Director Systems
Collins APS-80 Autopilot System
Universal UNS-1M FMS with Garmin 500 WAAS GPS
Collins Multi-Function Display
Dual Collins VHF-20B Comms
Dual Collins VIR-30A Navs
Dual Collins ADF-60 ADF's
Dual Collins RMI-36 RMI's
Dual Collins TDR-90 Transponders
Honeywell TCAS I
Collins WXT-300 Color Radar
Sandel TAWS
Collins Altitude Alert & Pre-Select
Collins HF-220 HF Comm
Dual Sperry C-14A Compass Systems
B & D Cockpit Voice Recorder
JET Standby Horizon with Battery Pack

Features: Thrust Reverse
Single Point Refueling
406 MHz ELT
RVSM Compliant

Maintenance: 200 Hr A Check next due 145 hours 400 Hr B Check next due 345 hours
800 Hr C Check next due 745 hours 4,800 Hr Structural Insp next due 2,278 hours

~

Aircraft is offered subject to prior sale, and/or removal from the market.
Specifications are subject to personal inspection of the aircraft.